

October 1, 2021

Company Name: TAKAOKA TOKO CO., LTD.
Name of representative PRESIDENT (Representative Director):
Takashi Ichinose (Cord: 6617 First Section of the Tokyo Stock Exchange)
Contact: DIRECTOR, MANAGING EXECUTIVE OFFICER
GENERAL MANAGER, Corporate Planning Department
Tatsuya Wakayama (Tel 03-6371-5002)

Temporary suspension of ISO9001 certification due to improper case of our Gas-Insulated Switchgear

We have received a notification on October 1 that our ISO9001^{※3} certification will be temporarily suspended after receiving a temporary inspection by the Electrical Safety and Environment Laboratory (JET), a registered certification organization of the ISO (International Organization for Standardization), after receiving a evidence of an improper incident (announced on August 27, 2021 and September 8, 2021) on two products of the cubicle-type gas-insulated switchgear (C-GIS)^{*1} and gas-insulated switchgear (GIS)^{*2} manufactured at our Oyama Plant.

We would like to express our deepest apologies again for causing great inconvenience and concern to our customers and related parties. In addition, we will strive to prevent recurrence and restore the trust of our customers, and make every effort to lift the temporary suspension of operations at an early stage.

- ※1 C-GIS: Cubicle-type Gas Insulated Switchgear
- ※2 GIS: Gas Insulated Switchgear
- ※3 ISO 9001: International standard for quality management systems

1. Our Target Business

Power Equipment & System Business, Electric Equipment Business, Metering Business, Energy Solution Business, and Applied Optics Inspection System Business.

2. Suspended Certification Standards

ISO 9001:2015

3. Certification Number

JET-0111

4. Date of temporary suspension of certification

October 1, 2021

At this time, we do not anticipate any revisions to the consolidated earnings forecast for the current fiscal year due to this matter. In the future, we will announce it as soon as possible if it is expected to have an impact.